



<b>PEUGEOT 5008: 1ERM178</b>			
Vinnumber:	<b>VF30A9HD8DS026678</b>	Versionname:	<b>5008 Access FAP 115PK</b>
First Registrationdate:	<b>1/03/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>137421</b>	Power Kw:	<b>84</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2532</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

<b>Options</b>	
Radio CD	Luggage cover
Windows electric F	
Cruise Control	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Manual climate control</b>

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>


<b>Degree of wear</b>				
	<b>215/5/16/97 H Steel</b>			
Winter tyres:	Fr.L.	<b>Kleber: 6 mm</b>	Fr.R.	<b>Kleber: 6 mm</b>
	Re.L.	<b>Uniroyal: 6 mm</b>	Re.R.	<b>Uniroyal: 6 mm</b>

<b>Assistance equipment</b>	
Emergency spare wheel	<b>Yes</b>

<b>Total cost ex VAT</b>	738,48
<b>Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)</b>	211,80



<b>Wing R R, Scratch(es), LI - Repair and paint (complete)</b>	0,00
--	------



Wheel cover F L, Scratch(es), E - Replace 30,00



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace 30,00



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace 30,00



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 0,00



Roof, Chemical pollution, LI - Repair and paint (complete) 0,00






Side window trim R L, Missing, E - Replace 20,00



Interior, Dirty, Cleaning 25,00



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 0,00



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete) 0,00



Floor covering F L, Hole, Smart repair 64,32



