




| VOLVO V60: 1FTC528 | | | |
|------------------------------------|--------------------------|--------------|---------------------------------|
| Vinnnumber: | YV1FW31A1E1172435 | Versionname: | V60 BRE D3 Kinetic 136PK |
| First Registrationdate: | 16/10/2013 | Fiscalpower: | |
| Expertise Mileage: | 161615 | Power Kw: | 100 |
| Bodytype: | Break | Body color: | Dark Brown |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 1307 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

| Options | | | |
|--------------------------------|------------------------------|----------------------|--------------------------|
| Radio CD | | Seats electric F L | |
| Windows electric F | | Central consol F | |
| Windows electric R | | Luggage cover | |
| Cruise Control | | Rear parking sensors | |
| Steering wheel multifunctional | | Type of Tow bar | Tow bar removable |
| Seats F heated | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |






















| Limited Technical Inspection | | | |
|------------------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

| Degree of wear | | | | |
|----------------|----------------------------------|-----------------------|-------|-----------------------|
| | 215/50/17/95 Y LightMetal | | | |
| Summer tyres: | Fr.L. | Uniroyal: 6 mm | Fr.R. | Uniroyal: 6 mm |
| | Re.L. | Pirelli: 6 mm | Re.R. | Pirelli: 6 mm |

| Assistance equipment | | | |
|---|------------|------------|----------------|
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 1677,52 |
| Door F L, Bump(s), LI - Repair and paint (complete) | | | 318,35 |



| | |
|---|---------------|
| Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) | 211,80 |
|---|---------------|

| | | | |
|---|---|--|--------|
|  |  |  | |
|  |  |  | |
| Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) | | | 318,35 |
|  |  | | |
| Wing F L, Scratch(es), LI - Repair and paint (complete) | | | 220,18 |
|  |  | | |
| Bumper R, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Alloy rim F L, Scratch(es), LI - Repair and paint (complete) | | | 95,00 |
|  |  |  | |
| Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) | | | 308,20 |
|  |  | | |
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | | | 95,00 |
|  |  |  | |
|  | | | |
| Alloy rim R R, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Front bumper, Scratch(es), Smart repair | | | 110,64 |
|  |  | | |