



| | | | |
|-------------------------------|--------------------------|--------------|--|
| SKODA Octavia: 1EHU153 | | | |
| Vinnumber: | TMBHT21Z4D2100163 | Versionname: | OCTAVIA COMBI GTec Ambition DPF 105PK |
| First Registrationdate: | 6/12/2012 | Fiscalpower: | |
| Expertise Mileage: | 128866 | Power Kw: | 77 |
| Bodytype: | Break | Body color: | Grey |
| Gearbox: | MAN 5 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3312 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

| | | | |
|--------------------------------|------------------------------|----------------------|--|
| Options | | | |
| Radio CD | | Central consol F | |
| GPS storage | HD | Luggage cover | |
| Windows electric F | | Rear parking sensors | |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS base | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Autom climate control | | |

| | | | |
|-------------------------------------|-----------|---------------------|------------|
| Limited Technical Inspection | | | |
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

| | | | | |
|-----------------------|----------------------------------|--------------------------|-------|--------------------------|
| Degree of wear | | | | |
| | 195/65/15/91 H LightMetal | | | |
| Winter tyres: | Fr.L. | Bridgestone: 5 mm | Fr.R. | Bridgestone: 5 mm |
| | Re.L. | Bridgestone: 6 mm | Re.R. | Bridgestone: 6 mm |

| | | | |
|--|------------|------|---------------|
| Assistance equipment | | | |
| Spare wheel | Yes | Jack | Yes |
| Total cost ex VAT | | | 518,20 |
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | | | 95,00 |




| | |
|----------------------------------|--------------|
| Door trim R L, Bad repair, Paint | 45,00 |
|----------------------------------|--------------|



Seat cover F L, Stain, Cleaning

25,00



Wing R L, Bad repair, LI - Repair and paint (complete)

308,20



Outer door handle R R, Scratch(es), Paint

45,00



Rearview mirror housing L, Scratch(es), Acceptable

0,00

No pictures to display