


TOYOTA AURIS TOURING SPORTS: 1NLU458

Vinnnumber:	SB1ZS3JE90E230575	Versionname:	1.8 HYBRID LOUNGE CVT AUTO
First Registrationdate:	21/03/2016	Fiscalpower:	
Expertise Mileage:	24602	Power Kw:	73
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Hybrid Petrol	Oil level:	OK
Maintenance:	24602	Parking lot:	1415
Maintenance:	OK		
Maintenance:	29/09/2017		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	HD	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining artificial leather and alcantara	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/91 W LightMetal			
Summer tyres:	Fr.L.	Dunlop: 7 mm	Fr.R.	Dunlop: 7 mm
	Re.L.	Dunlop: 7 mm	Re.R.	Dunlop: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1084,95
--------------------------	----------------

Alloy rim F L, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Wing R L, Bump(s) and scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	307,80
--	---------------



Dashboard, Scratch(es), Smart repair 110,64



Roof, No damage, P - Check 0,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper moulding R, Crack, E - Replace 114,52



Wing F L, Bump(s), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Scratch(es), 67 - Polish	55,19



Door R L, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	