



**AUDI A5: 1HRT312**

Vinnumber:	<b>WAUZZ8T4EA073547</b>	Versionname:	<b>A5 SB Multitr.DPF 150PK Aut.</b>
First Registrationdate:	<b>16/09/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>89798</b>	Power Kw:	<b>110</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>White</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1205</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining leather</b>
Type of climate control:	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>245/40/18/97 W LightMetal</b>				
Summer tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>
-----------------------	------------

Total cost ex VAT	2433,80
-------------------	---------

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete)

			Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00	
				Sill outer L, Bump(s) and scratch(es), LI - Repair and paint (complete)	372,60
			Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)	115,56	
			Bonnet, Chemical pollution, LI - Repair and paint (complete)	348,09	
			Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00	
				Door R L, Bump(s), PDR - Knock out without painting	63,00
			Door R R, Bump(s), LI - Repair and paint (complete)	382,02	
			Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)	254,16	



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 254,16



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00

