



BMW 3: 1FXC249

Vinnumber:	WBA3D91030J413199	Versionname:	3 BER 316d 116PK
First Registrationdate:	25/11/2013	Fiscalpower:	
Expertise Mileage:	75072	Power Kw:	85
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1428
Maintenance:	12000 KM		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	
GPS storage	HD
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/96 W LightMetal			
Summer tyres:	Fr.L.	Vredestein: 7 mm	Fr.R.	Vredestein: 7 mm
	Re.L.	Vredestein: 7 mm	Re.R.	Vredestein: 7 mm

























Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2249,08
-------------------	----------------

Interior, Dirty, Cleaning	50,00
---------------------------	--------------



			Wing R L, Scratch(es), 67 - Polish	55,19
			Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
			Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
			Wing F R, Bump(s), LI - Repair and paint (complete)	220,18
			Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete)	290,08
				
				
			Door R L, Bump(s), Acceptable	0,00
				
			Tailgate, Scratch(es), Acceptable	0,00
			Door F L, Bump(s) and scratch(es), Acceptable	0,00
			Roof, Chemical pollution, LI - Repair and paint (complete)	481,50



Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18



Door F R, Scratch(es), Acceptable 0,00



Alloy rim R L, Scratch(es), Acceptable 0,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35

