



BMW 1: 1GNP823

Vinnnumber:	WBA1C11090E885329	Versionname:	1 BER HATCH 118d 136PK
First Registrationdate:	19/03/2014	Fiscalpower:	
Expertise Mileage:	62604	Power Kw:	100
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2813
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		
Windows electric F		
Windows electric R		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/55/16/87 H Steel			
Winter tyres:	Fr.L.	Pirelli: 7 mm	Fr.R.	Pirelli: 7 mm
	Re.L.	Pirelli: 7 mm	Re.R.	Pirelli: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT

	1579,11
--	----------------

Wheel cover R R, Damaged, E - Replace

	30,00
--	--------------



Rear window, Scratch(es), Acceptable	0,00
--------------------------------------	-------------


No pictures to display

Door R.L. Bump(s), PDP, Knock out without painting **82,80**

Door R L, Bump(s), PDR - Knock out without painting 02,00



Bonnet, Bump(s), PDR - Knock out without painting 225,60



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80



Wheel cover F L, Deformed, E - Replace 30,00



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Rear spoiler, Scratch(es), Acceptable 0,00

No pictures to display

Steel rim R R, Damaged, E - Replace 88,80





Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Tailgate, Scratch(es), LI - Repair and paint (complete)	301,68
---	--------



Roof, Bump(s), Acceptable	0,00
---------------------------	------

No pictures to display