



<b>OPEL Insignia: 1EYH124</b>			
Vinnumber:	<b>WOLGT6EL8D1091657</b>	Versionname:	<b>INSIGNIA BER ecofl.Cosmo S/S DPF 130PK</b>
First Registrationdate:	<b>19/04/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>162836</b>	Power Kw:	<b>96</b>
Bodytype:	<b>Hatchback</b>	Body color	<b>Dark Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>3822</b>
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

<b>Options</b>	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunction	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining semi-artificial leather</b>
Type of climate control	<b>Autom climate control</b>

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>NOT OK</b>	Sound engine	<b>NOT OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
	<b>225/55/17/97 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Semperit: 2 mm</b>	Fr.R.	<b>Semperit: 2 mm</b>
	Re.L.	<b>Semperit: 3 mm</b>	Re.R.	<b>Semperit: 3 mm</b>

<b>Assistance equipment</b>			
Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>

Total cost ex VAT	<b>1639,42</b>
Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	<b>380,20</b>

Rocker panel inner F R, Scratch(es), LI - Repair and paint (complete)	<b>115,56</b>
---	---------------

Roof, Chemical pollution, LI - Repair and paint (complete)	<b>481,50</b>
--	---------------



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Front bumper, Scratch(es), LI - Repair and paint (complete)

211,80



Protection plate M, Hole, E - Replace

74,00



Rocker panel inner R R, Scratch(es), LI - Repair and paint (complete)

115,56



Inner seat cover L, Damaged, E - Replace

49,00



Bodywork, Scratch(es), 67 - Polish

0,00

