



**BMW 1: 1FSY390**

Vinnumber:	<b>WBA1C91070J517642</b>	Versionname:	<b>1 HATCH 116d Eff.Dyn.Ed. 116PK</b>
First Registrationdate:	<b>15/10/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>147508</b>	Power Kw:	<b>85</b>
Bodytype:		Body color	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Maintenance	<b>OK</b>	Parking lot	<b>3413</b>
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Radio CD		Central consol F
GPS storage	<b>HD</b>	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>NOT OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/91 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

























Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>1237,23</b>
-------------------	----------------

Door R R, Scratch(es), LI - Repair and paint (complete)	<b>318,35</b>
---	---------------



Bumper R, Scratch(es), Acceptable	<b>0,00</b>
-----------------------------------	-------------

			Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
			Sill outer L, Scratch(es), It - Spot repair	115,56
			Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
			Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
			Front bumper, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>				
			Wing R L, Bump(s), PDR - Knock out without painting	82,80
			Wing R R, Scratch(es), LI - Repair and paint (complete)	308,20
			Headlight L, Not functioning (well), Acceptable	0,00
			Backrest cover F R, Scratch(es), Smart repair	64,32
				
			Gear shift lever knob, Worn, Acceptable	0,00



Door F R, Bump(s), PDR - Knock out without painting

63,00

