


BMW 3: 1FH0600

Vinnumber:	WBA3K110X0F850465	Versionname:	3 TOURING 318dA 136PK
First Registrationdate:	1/07/2013	Fiscalpower:	Aut.
Expertise Mileage:	130792	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	3324
Maintenance:	1/02/2018		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Winter tyres:	Fr.L.	Goodyear: 9 mm	Fr.R.	Goodyear: 9 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT	1464,17		
Alloy rim F R, Scratch(es), Acceptable	0,00		
<i>No pictures to display</i>			
Front bumper, Scratch(es), Acceptable	0,00		
<i>No pictures to display</i>			
Alloy rim R L, Scratch(es), Acceptable	0,00		
<i>No pictures to display</i>			
Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08		



Rear spoiler, Chemical polution, LI - Repair and paint (complete) 115,56



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Windscreen, Stone chip(s), Acceptable 0,00

No pictures to display

Maintenance, Maintenance, Execute 0,00

No pictures to display

Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Door F L, Scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display