



|                              |                          |              |                                      |
|------------------------------|--------------------------|--------------|--------------------------------------|
| <b>DACIA Duster: 1FAD075</b> |                          |              |                                      |
| Vinnumber:                   | <b>UU1HSDACN48840814</b> | Versionname: | <b>DUSTER 4x4 Ambiance FAP 109PK</b> |
| First Registrationdate:      | <b>3/05/2013</b>         | Fiscalpower: |                                      |
| Expertise Mileage:           | <b>142518</b>            | Power Kw:    | <b>81</b>                            |
| Bodytype:                    |                          | Body color:  | <b>White</b>                         |
| Gearbox:                     | <b>MAN 5 VIT</b>         | Paint type:  | <b>Metalic</b>                       |
| Transmission:                |                          | Rims summer: | <b>Steel</b>                         |
| Fueltype:                    | <b>Diesel</b>            | Oil level:   | <b>OK</b>                            |
| Battery functioning:         | <b>Yes</b>               | Parking lot: | <b>2326</b>                          |
| Number of doors:             | <b>5</b>                 |              |                                      |
| Number of seats:             | <b>5</b>                 |              |                                      |
| Number head rests:           | <b>5</b>                 |              |                                      |
| Rims summer:                 | <b>Steel</b>             |              |                                      |
| Category:                    | <b>Passenger Car</b>     |              |                                      |
| Oil level:                   | <b>OK</b>                |              |                                      |

|                      |                             |
|----------------------|-----------------------------|
| <b>Options</b>       |                             |
| Radio CD             | Luggage cover               |
| Windows electric F   |                             |
| Type of headlighting | <b>Headlighting Halogen</b> |
| Type of Lining       | <b>Lining fabrics</b>       |

|                                     |               |                     |               |
|-------------------------------------|---------------|---------------------|---------------|
| <b>Limited Technical Inspection</b> |               |                     |               |
| Airco functioning                   | <b>NOT OK</b> | Battery functioning | <b>Yes</b>    |
| Tires wear profile                  | <b>OK</b>     | Power steering      | <b>Yes</b>    |
| Idle position                       | <b>OK</b>     | Sound engine        | <b>OK</b>     |
| Engine startingtime                 | <b>OK</b>     | Clutch test         | <b>OK</b>     |
| Exhaust gass                        | <b>OK</b>     | Wiper fluid level   | <b>NOT OK</b> |
| Handbrake                           | <b>OK</b>     | Transmission        | <b>OK</b>     |
|                                     |               | Lighting            | <b>OK</b>     |
|                                     |               | Wiperblades         | <b>OK</b>     |

|                       |                             |                          |       |                          |
|-----------------------|-----------------------------|--------------------------|-------|--------------------------|
| <b>Degree of wear</b> |                             |                          |       |                          |
|                       | <b>215/65/16/98 H Steel</b> |                          |       |                          |
| Summer tyres:         | Fr.L.                       | <b>Continental: 3 mm</b> | Fr.R. | <b>Continental: 3 mm</b> |
|                       | Re.L.                       | <b>Continental: 4 mm</b> | Re.R. | <b>Continental: 4 mm</b> |

|   |            |
|---|------------|
| <b>Assistance equipment</b>   |            |
| Spare wheel   | <b>Yes</b> |
| Total cost ex VAT   | 2569,89    |
| Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) | 308,20     |



|  |       |
|--|-------|
| Rocker panel inner F L, Damaged, E - Replace | 44,00 |
|--|-------|



|   |        |
|---|--------|
| Sill outer L, Damaged, Le - Replace and paint | 298,00 |
|---|--------|



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Tailgate, Bump(s), LI - Repair and paint (complete) 301,68



Wing F R, Bump(s), LI - Repair and paint (complete) 220,18



Sill outer R, Damaged, Le - Replace and paint 298,00



Front bumper, Bump(s), Smart repair 110,64



Bumper R, Bump(s) and scratch(es), Smart repair 110,64



Floor covering F L, Damaged, E - Replace 252,00

