



**MASERATI GIBLI: 1NGR142**

|                         |                          |              |                     |
|-------------------------|--------------------------|--------------|---------------------|
| Vinnumber:              | <b>ZAMTS57B001168686</b> | Versionname: | <b>3.0D AUTO</b>    |
| First Registrationdate: | <b>19/02/2016</b>        | Fiscalpower: |                     |
| Expertise Mileage:      | <b>57411</b>             | Power Kw:    | <b>202</b>          |
| Bodytype:               | <b>Berline</b>           | Body color:  | <b>Grey</b>         |
| Gearbox:                | <b>Automatic</b>         | Paint type:  | <b>Metalic</b>      |
| Transmission:           |                          | Rims summer: | <b>Aluminium</b>    |
| Fueltype:               |                          | Oil level:   | <b>NOT OK</b>       |
| Battery functioning:    | <b>No</b>                | Parking lot: | <b>DEP 2000 408</b> |
| Number of doors:        | <b>4</b>                 |              |                     |
| Number of seats:        | <b>4</b>                 |              |                     |
| Number head rests:      | <b>4</b>                 |              |                     |
| Rims summer:            | <b>Aluminium</b>         |              |                     |
| Category:               | <b>Passenger Car</b>     |              |                     |
| Oil level:              | <b>NOT OK</b>            |              |                     |

**Options**

|                       |                             |                        |  |
|-----------------------|-----------------------------|------------------------|--|
| Type of headlighting: | <b>Headlighting Halogen</b> | Front parking sensors: |  |
| Type of Lining:       | <b>Lining leather</b>       | Rear parking sensors:  |  |

**Limited Technical Inspection**

|                      |               |                      |               |
|----------------------|---------------|----------------------|---------------|
| Airco functioning:   | <b>NOT OK</b> | Battery functioning: | <b>No</b>     |
| Tires wear profile:  | <b>NOT OK</b> | Power steering:      | <b>No</b>     |
| Idle position:       | <b>NOT OK</b> | Sound engine:        | <b>NOT OK</b> |
| Engine startingtime: | <b>NOT OK</b> | Clutch test:         | <b>NOT OK</b> |
| Exhaust gass:        | <b>NOT OK</b> | Wiper fluid level:   | <b>NOT OK</b> |
| Handbrake:           | <b>NOT OK</b> | Transmission:        | <b>NOT OK</b> |
|                      |               | Lighting:            | <b>NOT OK</b> |
|                      |               | Wiperblades:         | <b>NOT OK</b> |

**Degree of wear**

|               |                             |             |       |             |
|---------------|-----------------------------|-------------|-------|-------------|
|               | <b>0/0/0/0 A LightMetal</b> |             |       |             |
| Summer tyres: | Fr.L.                       | <b>N.D.</b> | Fr.R. | <b>N.D.</b> |
|               | Re.L.                       | <b>N.D.</b> | Re.R. | <b>N.D.</b> |

**Assistance equipment**

|                               |      |
|-------------------------------|------|
| Total cost ex VAT             | 0,00 |
| Bodywork, Accident, No repair | 0,00 |



