


**MERCEDES A: 1JHT487**

Vinnnumber:	<b>WDD1760121V046545</b>	Versionname:	<b>1.5 A 180 CDI</b>
First Registrationdate:	<b>23/12/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>69373</b>	Power Kw:	<b>80</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2404</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining semi-leather</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/45/17/91 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 4 mm</b>	Fr.R.	<b>Bridgestone: 4 mm</b>
	Re.L.	<b>Bridgestone: 7 mm</b>	Re.R.	<b>Bridgestone: 7 mm</b>







**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			3033,79
Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)			211,80



Wing R R, Bump(s) and scratch(es), Acceptable

0,00

Door R L, Chemical polution, LI - Repair and paint (complete)	318,35
	
Sill outer R, Damaged, Le - Replace and paint	712,00
	
Roof, Chemical polution, LI - Repair and paint (complete)	481,50
	
Wing R L, Chemical polution, LI - Repair and paint (complete)	308,20
	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
	
Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
	
Door R R, Scratch(es), Acceptable	0,00
No pictures to display	
Roof pillar L, Chemical polution, LI - Repair and paint (complete)	220,18



Tailgate, Chemical pollution, LI - Repair and paint (complete)

301,68



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00

