



## PEUGEOT 5008: 1EZB418

Vinnnumber:	<b>VF30E9HD8DS079017</b>	Versionname:	<b>5008 e-HDi Active FAP BMP 115PK Aut.</b>
First Registrationdate:	<b>25/04/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>178622</b>	Power Kw:	<b>84</b>
Bodytype:	<b>MPV</b>	Body color	<b>Black</b>
Gearbox:	<b>Automatic</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>2228</b>
Number of doors	<b>5</b>		
Number of seats	<b>7</b>		
Number head rests	<b>7</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

## Options

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>NOT OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>215/55/16/93 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Fulda: 7 mm</b>	Fr.R.	<b>Fulda: 7 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

## Assistance equipment

Spare wheel	<b>Yes</b>
-------------	------------

Total cost ex VAT	933,35
-------------------	--------

Luggage space cover, Missing, E - Replace	0,00
---	------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Ignition key, Missing, E - Replace	0,00
------------------------------------	------

No pictures to display

Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display


Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Maintenance book, Missing, E - Replace 0,00

No pictures to display


Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R L, Bump(s), Acceptable 0,00

No pictures to display

Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Door F L, Bump(s), Acceptable 0,00

No pictures to display

Door F R, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Roof, Hail damage, PDR - Hail 0,00



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35

