



**OPEL Astra BREAK: 1FAN343**

Vinnnumber:	<b>W0LPD8EW3D8053411</b>	Versionname:	<b>ASTRA BRE ecoFL.Enjoy Active St/St 110PK</b>
First Registrationdate:	<b>7/05/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>98319</b>	Power Kw:	<b>81</b>
Bodytype:	<b>Break</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2113</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>No</b>		

**Options**

Radio CD		Rear parking sensors	
GPS storage	<b>SD</b>		
GPS storage			
Windows electric F			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>215/60/16/99 H Steel</b>			
Winter tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Semperit: 4 mm</b>	Re.R.	<b>Semperit: 4 mm</b>

**Assistance equipment**

Repair kit	<b>No</b>	Jack	<b>Yes</b>
Total cost ex VAT			<b>3252,87</b>
Tyre repair kit, Missing, E - Replace			<b>210,53</b>



Door R R, Scratch(es), LI - Repair and paint (complete)	<b>0,00</b>
---	-------------



	<b>0,00</b>
--	-------------

Door F L, Scratch(es), LI - Repair and paint (complete) 318,35



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 428,20



Inner door handle F L, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete) 338,08



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Roof pillar L, Chemical polution, LI - Repair and paint (complete) 220,18



Inner door handle F R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), LI - Repair and paint (complete) 0,00



Luggage space cover, Missing, E - Replace 240,00



Tailgate, Bump(s), LI - Repair and paint (complete) 397,68



Windscreen, Stone chip(s), Acceptable	0,00
---------------------------------------	------

*No pictures to display*

Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Door R L, Chemical pollution, LI - Repair and paint (complete)	318,35
--	--------



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------



Wheel cover F R, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Trunk lid covering R, Scratch(es), Acceptable	0,00
---	------

*No pictures to display*

Registration Document, Missing, E - Replace	150,00
---	--------

