



TOYOTA AURIS: 1NRF546			
Vinnumber:	SB1MS3JE10E247039	Versionname:	1.8 HYBRID LOUNGE CVT
First Registrationdate:	7/04/2016	Fiscalpower:	AUTO
Expertise Mileage:	47513	Power Kw:	73
Bodytype:		Body color:	GRIS
Gearbox:	Automatic	Body color:	Grey
Transmission:	Front	Paint type:	Metalic
Fueltype:	Hybrid Petrol	Rims summer:	Aluminium
Battery functioning:	Yes	Oil level:	OK
Number of doors:	5	Parking lot:	1328
Number of seats:	5		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/45/17/91 W LightMetal			
Summer tyres:	Fr.L.	Dunlop: 3 mm	Fr.R.	Dunlop: 3 mm
	Re.L.	Dunlop: 4 mm	Re.R.	Dunlop: 4 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			984,00
Boot cover, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)			95,00





Rocker panel inner R L, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Broken, E - Replace 487,20



Tyre F R, Tear, Acceptable 0,00



Seat cover F L, Stain, Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Tyre F L, Tear, Acceptable 0,00



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80





Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing F L, Not original part, Acceptable	0,00
---	------

No pictures to display

Door R R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Bumper moulding R Mid, Damaged, Acceptable	0,00
--	------

No pictures to display