


TOYOTA AVENSIS TOURING SPORTS: 1NLZ723

| | | | |
|------------------------------------|--------------------------|--------------|--|
| Vinnumber: | SB1EG76L80E119434 | Versionname: | 1.8 VALVEMATIC DYNAMIC+ MD S AUTO |
| First Registrationdate: | 22/03/2016 | Fiscalpower: | |
| Expertise Mileage: | 52436 | Power Kw: | 108 |
| Bodytype: | | Body color: | Black |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 1714 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|---------------------------------------|----------------------|--------------------------|
| GPS storage | | Central consol F | |
| GPS storage | HD | Luggage cover | |
| Windows electric F | | Rear parking sensors | |
| Windows electric R | | Type of Tow bar | Tow bar removable |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining semi-artificial leather | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
| | 245/45/18/95 V LightMetal | | | |
| Summer tyres: | Fr.L. | Bridgestone: 4 mm | Fr.R. | Bridgestone: 4 mm |
| | Re.L. | Bridgestone: 4 mm | Re.R. | Bridgestone: 4 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|---------------|
| Total cost ex VAT | 711,38 |
|-------------------|---------------|

| | |
|-----------------------------------|-------------|
| Door R R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|-------------|



| | |
|--|--------------|
| Alloy rim F L, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|--------------|



Interior, Smell, Ozone treatment 152,58

No pictures to display

Boot carpet, Dirty, Cleaning 25,00



Sill outer R, Scratch(es), Acceptable 0,00



Armrest F Mid, Worn, Acceptable 0,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Bumper corner R R, Scratch(es), Acceptable 0,00



Tyre F R, Damaged, E - Replace 132,00



Wing R R, Scratch(es), Acceptable 0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00

