



BMW 2 GRAN TOURER: CN6088

| | | | |
|-------------------------|--------------------------|--------------|--|
| Vinnumber: | WBA2D710005C39152 | Versionname: | 2.0 220D (140KW) XDRIVE GRAN TOURER |
| First Registrationdate: | 8/12/2015 | Fiscalpower: | |
| Expertise Mileage: | 115109 | Power Kw: | 140 |
| Bodytype: | MPV | Body color: | Black |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2224 |
| Number of doors: | 5 | | |
| Number of seats: | 7 | | |
| Number head rests: | 7 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

Options

| | |
|--------------------------------|------------------------------|
| Windows electric F | Seats electric F L |
| Windows electric R | Seats electric F R |
| Cruise Control | Sun Roof electric |
| Steering wheel multifunctional | Panoramic roof |
| Seats F heated | Central consol F |
| Type of headlighting | Headlighting LED |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining leather |
| Type of climate control | Autom climate control |
| Sport seats | Luggage cover |
| | Front parking sensors |
| | Rear parking sensors |
| | Type of Tow bar |
| | Tow bar removable |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
| | 205/55/17/91 H LightMetal | | | |
| Winter tyres: | Fr.L. | Continental: 4 mm | Fr.R. | Continental: 4 mm |
| | Re.L. | Continental: 6 mm | Re.R. | Continental: 6 mm |

Assistance equipment

| | |
|---|--------|
| Total cost ex VAT | 753,48 |
| Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) | 95,00 |



| | |
|---|-------|
| Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|---|-------|



| | |
|---|--------|
| Wing R L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door F L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door F R, Bump(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper R, Scratch(es), LI - Repair and paint (complete) | 211,80 |



| | |
|---|--------|
| Door R R, Bump(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Rocker panel inner R R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete) | 301,68 |



| | |
|---------------------------|-------|
| Interior, Stain, Cleaning | 50,00 |
|---------------------------|-------|

