



BMW 3: 1FCY739

| | | | |
|-------------------------|--------------------------|--------------|-----------------------------|
| Vinnumber: | WBA3K91040F930696 | Versionname: | 3 TOURING 316d 116PK |
| First Registrationdate: | 28/05/2013 | Fiscalpower: | |
| Expertise Mileage: | 121687 | Power Kw: | 85 |
| Bodytype: | Break | Body color: | Dark Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 1711 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

Options

| | |
|------------------------------|----------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | |
| Cruise Control | |
| Steering wheel multifunction | |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining artificial leather |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear


| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| | 205/60/16/92 W LightMetal | | | |
| Summer tyres: | Fr.L. | Goodyear: 5 mm | Fr.R. | Goodyear: 5 mm |
| | Re.L. | Goodyear: 4 mm | Re.R. | Goodyear: 4 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|---------------|
| Total cost ex VAT | 423,60 |
|-------------------|---------------|

| | |
|---|---------------|
| Front bumper, Bump(s), LI - Repair and paint (complete) | 211,80 |
|---|---------------|



| | |
|-------------------------------|-------------|
| Door F L, Bump(s), Acceptable | 0,00 |
|-------------------------------|-------------|


No pictures to display

| | |
|----------------------------------|-------------|
| Seat cover F L, Worn, Acceptable | 0,00 |
|----------------------------------|-------------|

Seat cover L, worn, Acceptable 0,00



Bumper R, Bump(s), LI - Repair and paint (complete) 211,80



Wing R R, Bump(s), Acceptable 0,00

No pictures to display