



BMW 3: 1GRU378

Vinnumber:	WBA3K11000F831858	Versionname:	3 TOURING 318d 136PK
First Registrationdate:	10/04/2014	Fiscalpower:	
Expertise Mileage:	88146	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3118
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/91 MS LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment






















Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	3169,67
-------------------	----------------

Roof, Bump(s), PDR - Knock out without painting	63,00
---	--------------



Door R L, Scratch(es), LI - Repair and paint (complete)	318,35
---	---------------

		Bumper F R, Scratch(es), It - Spot repair	115,56	
		Door R R, Bump(s), PDR - Knock out without painting	63,00	
		Bumper R, Crack, Le - Replace and paint	651,00	
		Wing R L, Bump(s), PDR - Knock out without painting	63,00	
		Alloy rim R R, Scratch(es), Acceptable	0,00	
<i>No pictures to display</i>				
Rear window, Scratch(es), E - Replace			370,00	
			Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
		Foglight L, Crack, E - Replace	138,00	
		Wing R R, Bump(s), PDR - Knock out without painting	63,00	
		Tailgate, Bump(s), Le - Replace and paint	1034,68	
		Bumper F L, Scratch(es), Acceptable	0,00	
<i>No pictures to display</i>				

