


OPEL Vivaro 2700: 1FTZ385

Vinnnumber:	WOLF7A1A6DV618400	Versionname:	VIVARO 2700 B/F SWB L1H1(EU5)115PK
First Registrationdate:	24/10/2013	Fiscalpower:	
Expertise Mileage:	67015	Power Kw:	84
Bodytype:		Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV06
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Rear parking sensors
Windows electric F		
Cruise Control		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/65/16/105 T Steel			
Winter tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Michelin: 8 mm	Re.R.	Michelin: 8 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1517,12
-------------------	----------------

Bodywork, Not original part, Remove lettering	0,00
---	-------------

No pictures to display

Wing R L, Bump(s), Acceptable	0,00
-------------------------------	-------------



Bumper Trim F, Scratch(es), It - Spot repair	115,86
--	---------------



Front bumper, Scratch(es), LI - Repair and paint (complete)	158,85
---	---------------




Wheel cover R R, Scratch(es), E - Replace 22,50



Seat cover F R, Stain, Acceptable 0,00

No pictures to display

Roof, Bump(s), LI - Repair and paint (complete) 433,13



Tailgate, Bump(s), LI - Repair and paint (complete) 458,02



Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete) 217,56



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Trunk lid covering R, Damaged, Acceptable 0,00

No pictures to display

Grill frame, Scratch(es), E - Replace 89,00



Door R R, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover F R, Missing, E - Replace	22,50



Seat cover F L, Stain, Acceptable	0,00
<i>No pictures to display</i>	
Boot carpet, Damaged, Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror housing R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	