



MINI ONE COOPER: 1EXL222

Vinnnumber:	WMWSW31020T232411	Versionname:	MINI Cooper D 112PK DPF
First Registrationdate:	15/04/2013	Fiscalpower:	
Expertise Mileage:	132943	Power Kw:	82
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2522
Number of doors:	3		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
GPS storage	Rear parking sensors
GPS storage	HD
Windows electric F	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	175/65/15/84 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	N.D.	Re.R.	N.D.
	175/65/15/84 T LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 0 mm	Fr.R.	Uniroyal: 0 mm
	Re.L.	Uniroyal: 2 mm	Re.R.	Uniroyal: 2 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1058,80
Bumper R, Scratch(es), LI - Repair and paint (complete)	259,80



Boot cover, Missing, E - Replace	50,00
---	--------------



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 404,20



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Spoiler F R, Scratch(es), Acceptable 0,00

No pictures to display

Tires, Not original part, P - Check 0,00

No pictures to display

Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Spoiler R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Repaired, P - Check 0,00



Door F R, Repaired, P - Check 0,00



Wing trim R L, Scratch(es), E - Replace 84,00



Tailgate, Not original part, Remove lettering 25,00



Front bumper, Bump(s), LI - Repair and paint (complete) 235,80



Door F L, Bump(s), Acceptable 0,00

No pictures to display