



<b>MINI Countryman: 1AMJ344</b>			
Vinnumber:	<b>WMWZD31060WK46900</b>	Versionname:	<b>MINI COUNTRYMAN Cooper D DPF 112PK</b>
First Registrationdate:	<b>8/02/2011</b>	Fiscalpower:	
Expertise Mileage:	<b>141100</b>	Power Kw:	<b>82</b>
Bodytype:		Body color:	<b>Red</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4233</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

<b>Options</b>	
Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Rear parking sensors
Type of headlighting	<b>Headlighting Halogen</b>
Type of Lining	<b>Lining semi-leather</b>
Type of climate control	<b>Autom climate control</b>

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
	<b>205/55/17/91 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 5 mm</b>	Fr.R.	<b>Bridgestone: 5 mm</b>
	Re.L.	<b>Vredestein: 7 mm</b>	Re.R.	<b>Vredestein: 7 mm</b>

<b>Assistance equipment</b>			
Repair kit	<b>No</b>	Compressor	<b>Yes</b>

<b>Total cost ex VAT</b>	<b>1823,52</b>
--------------------------	----------------









<b>Rearview mirror housing R, Scratch(es), Acceptable</b>	<b>0,00</b>
---	-------------

<i>No pictures to display</i>	
<b>Windscreen, Crack, E - Replace</b>	<b>0,00</b>



<b>Steering wheel, Worn, Acceptable</b>	<b>0,00</b>
---	-------------



Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
	
Door catch R R, Scratch(es), E - Replace	50,00
	
Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80
	
Door panel F R, Stain, Acceptable	0,00
	
Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete)	220,18
	
Rearview mirror housing L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door panel R L, Damaged, Smart repair	110,64
	
Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
	
Front bumper, Damaged, E - Replace	499,20
	
Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35

