


RENAULT Clio: 1GVV881

Vinnnumber:	VF15RJL0H50895018	Versionname:	CLIO IV BER e-Expression St&St 90PK
First Registrationdate:	14/05/2014	Fiscalpower:	
Expertise Mileage:	75849	Power Kw:	66
Bodytype:		Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4614
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Luggage cover	
GPS storage	HD		
Windows electric F			
Cruise Control			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/88 T Steel			
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1061,70
-------------------	---------



















Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	193,44
---	--------



Roof, Bump(s), Acceptable	0,00
---------------------------	------

No pictures to display

Wing F.R. Scratch(es), Acceptable	0,00
-----------------------------------	------

Wing F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Grill frame, Broken, E - Replace	64,00
	
Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)	217,44
	
	
	
Wheel cover F L, Damaged, E - Replace	24,00
	
Seat cover F L, Stain, Acceptable	0,00
<i>No pictures to display</i>	
Outer valance R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Scratch(es), LI - Repair and paint (complete)	254,68
	
Wheel cover R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover R R, Scratch(es), E - Replace	24,00
	
Wing R R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Wing F L, Scratch(es), LI - Repair and paint (complete)	176,14
	
	
Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover F R, Scratch(es), E - Replace	24,00
	
Trunk lid covering R, Scratch(es), E - Replace	84,00

