



RENAULT ESPACE: 1EUQ845

Vinnumber:	VF1JKFJC648542351	Versionname:	
First Registrationdate:		Fiscalpower:	
Expertise Mileage:	208906	Power Kw:	110
Bodytype:	MPV	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2826
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Sun Roof electric	
Windows electric F	Panoramic roof	
Windows electric R	Central consol F	
Cruise Control	Luggage cover	
Steering wheel multifunctional	Rear parking sensors	
Radio multimedia	Type of Tow bar	Tow bar removable
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather and alcantara	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/101 V Steel			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Spare wheel **Yes**

Total cost ex VAT **3246,70**

Door F R, Scratch(es), LI - Repair and paint (complete) **382,02**



Wheel cover R L, Missing, E - Replace

36,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Bump(s), LI - Repair and paint (complete) 369,84



Door R R, Scratch(es), LI - Repair and paint (complete) 382,02




Wheel cover F R, Missing, E - Replace 36,00



Interior, Dirty, Cleaning 0,00



Bonnet, Chemical polution, LI - Repair and paint (complete) 348,09



Wheel cover F L, Missing, E - Replace 36,00



Tailgate, Scratch(es), LI - Repair and paint (complete) 362,02



Wheel cover R R, Missing, E - Replace 36,00



Bumper R, Scratch(es), Smart repair 110,64



Door moulding Lower R L, Scratch(es), E - Replace 132,00



Wing F R, Scratch(es), LI - Repair and paint (complete) 264,21



Door R L, Scratch(es), LI - Repair and paint (complete) 382,02



Wing R L, Scratch(es), LI - Repair and paint (complete) 369,84

