



<b>PEUGEOT 2008: 1GWH538</b>			
Vinnumber:	<b>VF3CU8HR0EY006448</b>	Versionname:	<b>2008 Active 68PK</b>
First Registrationdate:	<b>19/05/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>77500</b>	Power Kw:	<b>50</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>3425</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

<b>Options</b>	
GPS storage	Luggage cover
GPS storage	<b>HD</b> Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Manual climate control</b>

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>















<b>Degree of wear</b>				
	<b>195/60/16/89 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Goodyear: 3 mm</b>	Fr.R.	<b>Goodyear: 3 mm</b>
	Re.L.	<b>Goodyear: 5 mm</b>	Re.R.	<b>Goodyear: 5 mm</b>


<b>Assistance equipment</b>			
Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>

<b>Total cost ex VAT</b>	<b>1025,12</b>
<b>Front bumper, Scratch(es), LI - Repair and paint (complete)</b>	<b>211,80</b>



<b>Wheel cover R L, Scratch(es), Acceptable</b>	<b>0,00</b>
---	-------------

<i>No pictures to display</i>		
Tyre F R, Worn, Forfeit		0,00
		
Wheel cover F R, Scratch(es), Acceptable		0,00
		
Wing R R, Bump(s), Acceptable		0,00
<i>No pictures to display</i>		
Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete)		220,18
		
Maintenance book, Missing, E - Replace		0,00
<i>No pictures to display</i>		
Tyre F L, Worn, Forfeit		0,00
		
Wheel cover F L, Scratch(es), Acceptable		0,00
		
Certificate Of Conformity, Missing, E - Replace		150,00
<i>No pictures to display</i>		
Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)		115,56
		
Instruction book, Missing, E - Replace		0,00
<i>No pictures to display</i>		
Ignition key, Missing, E - Replace		150,00
<i>No pictures to display</i>		
Interior, Dirty, Cleaning		25,00
		
		
Interior, Smell, Ozone treatment		152,58



Wing F L, Bump(s), Acceptable

0,00

*No pictures to display*