



## VOLKSWAGEN TIGUAN: 1GHM417

Vinnnumber:	<b>WVGZZ5NZEW572480</b>	Versionname:	<b>TIGUAN Sport&amp;Style BM</b>
First Registrationdate:	<b>10/02/2014</b>	Fiscalpower:	<b>Tech.140PK</b>
Expertise Mileage:	<b>87250</b>	Power Kw:	<b>103</b>
Bodytype:	<b>Off-road</b>	Body color:	<b>Dark Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>2806</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD		Seats electric F L
GPS storage		Sun Roof electric
GPS storage	<b>HD</b>	Panoramic roof
Windows electric F		Central consol F
Windows electric R		Luggage cover
Cruise Control		Front parking sensors
Steering wheel multifunctional		Rear parking sensors
Seats F heated		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear


	<b>235/55/17/103 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Fulda: 7 mm</b>	Fr.R.	<b>Fulda: 7 mm</b>
	Re.L.	<b>Fulda: 7 mm</b>	Re.R.	<b>Fulda: 7 mm</b>
	<b>235/55/17/103 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Fulda: 8 mm</b>	Fr.R.	<b>Fulda: 8 mm</b>
	Re.L.	<b>Fulda: 8 mm</b>	Re.R.	<b>Fulda: 8 mm</b>

## Assistance equipment

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>1009,20</b>
Wing F L, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Alloy rim R R, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Alloy rim R L, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Alloy rim F R, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Alloy rim F L, Scratch(es), 1 - Repair			<b>0,00</b>



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Bumper R, Deformed, E - Replace 415,20



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Cupholder R, Damaged, E - Replace 74,00



Door F L, Scratch(es), Acceptable 0,00

*No pictures to display*

Door R R, Bump(s), Acceptable 0,00

*No pictures to display*

Rearview mirror housing R, Scratch(es), Acceptable 0,00

*No pictures to display*