



BMW 5: 1GWX465

Vinnnumber:	WBA5J11000D065816	Versionname:	5 TOURING 518dA 136PK Aut.
First Registrationdate:	22/05/2014	Fiscalpower:	
Expertise Mileage:	189916	Power Kw:	100
Bodytype:		Body color	Brown
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	4615
Maintenance	SEPTEMBER 2019		
Maintenance	7000		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Seats electric F R	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar fixed
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 Y LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 8 mm	Fr.R.	Uniroyal: 8 mm
	Re.L.	Uniroyal: 8 mm	Re.R.	Uniroyal: 8 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	976,74
-------------------	---------------

Outer door handle F L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Bodywork, Not original part, Acceptable	0,00
---	-------------

No pictures to display

Alloy rim R R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Internal Boot Lining R, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Door panel F L, Damaged, Acceptable	0,00
-------------------------------------	-------------

No pictures to display

No pictures to display	
Tailgate, Bump(s), Acceptable	0,00
No pictures to display	
Bumper R, Bump(s) and scratch(es), Acceptable	0,00
No pictures to display	
Rearview mirror basis R, Scratch(es), Acceptable	0,00
No pictures to display	
Seat F L compl, Worn, Acceptable	0,00
No pictures to display	
Door R L, Bump(s), PDR - Knock out without painting	63,00



Windscreen, Stone chip(s), Windscreen repair	58,80
--	-------



Mirror side blinker L, Waterinfiltration, E - Replace	31,20
---	-------



Door F R, Scratch(es), LI - Repair and paint (complete)	430,02
---	--------



Door F L, Bump(s) and scratch(es), It - Spot repair	115,56
---	--------



Trunk lid covering R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Rear bulkhead lining, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display

Internal Boot Lining L, Scratch(es), Acceptable	0,00
---	------

Internal Boot Lining L, Scratch(es), Acceptable	0,00
No pictures to display	
Wing R R, Bump(s) and scratch(es), Acceptable	0,00
No pictures to display	
Rearview mirror basis L, Scratch(es), Acceptable	0,00
No pictures to display	
Front bumper, Scratch(es), LI - Repair and paint (complete)	278,16
	
Wing R L, Bump(s) and scratch(es), Acceptable	0,00
No pictures to display	
Door frame R R, Scratch(es), Acceptable	0,00
No pictures to display	
Door R R, Scratch(es), Acceptable	0,00
No pictures to display	