



FORD Grand C-Max: 1LXB664

Vinnnumber:	WF0HXXWPBHET28957	Versionname:	GR.C-MAX Trend St/St
First Registrationdate:	21/05/2014	Fiscalpower:	95PK
Expertise Mileage:	89347	Power Kw:	70
Bodytype:		Body color	Brown
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	4701
Battery functioning	Yes		
Number of doors	5		
Number of seats	6		
Number head rests	6		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/55/16/93 H LightMetal				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm





Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1531,67
Wing F L, Scratch(es), LI - Repair and paint (complete)			220,18



Bonnet, Scratch(es), LI - Repair and paint (complete)

290,08

  		Gear shift lever cover, Tear, E - Replace	12,00
 		Seat cover R R, Stain, Cleaning	25,00
 		Front bumper, Scratch(es), Acceptable	0,00
No pictures to display		Windscreen, Stone chip(s), Acceptable	0,00
No pictures to display		Door F R, Scratch(es), Acceptable	0,00
No pictures to display		Door R R, Scratch(es), LI - Repair and paint (complete)	318,35
  			
			
		Ignition key, Not functioning (well), Repair/replace (lump sum)	0,00
No pictures to display		Interior, Smell, Ozone treatment	152,58
  			
			
  		Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
 			
 		Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete)	301,68



Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display