



BMW 3: 1GWI475

Vinnnumber:	WBA3K91050F934062	Versionname:	3 TOURING 316d 116PK
First Registrationdate:	19/05/2014	Fiscalpower:	
Expertise Mileage:	130992	Power Kw:	85
Bodytype:		Body color	Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	3627
Maintenance	25000		
Maintenance	JANUARI 2019		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS base
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 W LightMetal			
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	330,80
-------------------	--------

Internal Boot Lining R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Trunk lid covering R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Front bumper, Bad repair, Acceptable	0,00
--------------------------------------	------



Alloy rim R R, Scratch(es), Acceptable	0,00
No pictures to display	
Door panel R R, Damaged, Acceptable	0,00
No pictures to display	
Rear bulkhead lining, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper R, Repaired, Acceptable	0,00
No pictures to display	
Door panel F L, Damaged, Acceptable	0,00
No pictures to display	
Bodywork, Not original part, Acceptable	0,00
No pictures to display	
Door F L, Scratch(es), Acceptable	0,00
No pictures to display	
Door F R, Bump(s) and scratch(es), Acceptable	0,00
No pictures to display	
Tailgate, Repaired, Acceptable	0,00
No pictures to display	
Alloy rim R L, Scratch(es), Acceptable	0,00
No pictures to display	
Door panel R L, Damaged, Acceptable	0,00
No pictures to display	
Bumper R, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim F R, Damaged, LI - Repair and paint (complete)	95,00



Wing R R, Scratch(es), Acceptable	0,00
No pictures to display	
Internal Boot Lining L, Scratch(es), Acceptable	0,00
No pictures to display	
Door R L, Bump(s) and scratch(es), Acceptable	0,00
No pictures to display	
Front bumper, Damaged, LI - Repair and paint (complete)	235,80



Wing F R, Scratch(es), Acceptable	0,00
No pictures to display	
Seat F L compl, Worn, Acceptable	0,00



Wing F L, Repaired, Acceptable	0,00
--------------------------------	------

No pictures to display

Windscreen, Stone chip(s), Acceptable	0,00
---------------------------------------	------

No pictures to display

Wing R L, Bump(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Door R L, Bad repair, Acceptable	0,00
----------------------------------	------

