


OPEL ASTRA: XT6818

Vinnnumber:	WOLBE6ELXGG114281	Versionname:	1.6 CDTI 81KW ECOFLEX S/S INNOVATION
First Registrationdate:	25/05/2016	Fiscalpower:	
Expertise Mileage:	45078	Power Kw:	81
Bodytype:		Body color	Light Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	2814
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

GPS storage	HD	Sun Roof electric
GPS storage		Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Bridgestone: 8 mm	Re.R.	Bridgestone: 8 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

















Total cost ex VAT	1034,86
Door frame R L, Bump(s) and scratch(es), It - Spot repair	115,56



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim F L, Damaged, E - Replace	235,20
-------------------------------------	--------

			
Door R R, Scratch(es), LI - Repair and paint (complete)			318,35
			
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)			95,00
			
Interior, Waterinfiltration, Cleaning			100,00
			
			
Windscreen, Repaired, Acceptable			0,00
<i>No pictures to display</i>			
Headlight R, Scratch(es), 67 - Polish			55,19
			
Front bumper, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door F L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door frame R R, Bump(s) and scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)			115,56
