



TOYOTA AURIS: 1LNA776

Vinnumber:	SB1MS3JE60E198999	Versionname:	1.8 HYBRID LOUNGE CVT AUTO
First Registrationdate:	26/10/2015	Fiscalpower:	
Expertise Mileage:	31106	Power Kw:	100
Bodytype:		Body color:	Red
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Hybrid	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3710
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Central consol F
GPS storage		Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting LED	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/91 W LightMetal			
Summer tyres:	Fr.L.	Dunlop: 0 mm	Fr.R.	Dunlop: 0 mm
	Re.L.	Dunlop: 0 mm	Re.R.	Dunlop: 0 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			464,80
Bumper R, Scratch(es), Acceptable			0,00



Rocker panel inner R R, Bump(s), Acceptable			0,00
---	--	--	-------------



Wing R L, Scratch(es), Acceptable 0,00



Tailgate, Scratch(es), Acceptable 0,00



Door R R, Bump(s), PDR - Knock out without painting 63,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R L, Bump(s), Acceptable 0,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Door R R, Bump(s), Acceptable 0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00

