



VOLKSWAGEN Touran: 1EOJ387

Vinnnumber:	WVGZZZ1TZDW074578	Versionname:	TOURAN Trendline BMT
First Registrationdate:	6/02/2013	Fiscalpower:	Start/Stop 105PK
Expertise Mileage:	118783	Power Kw:	77
Bodytype:	Hatchback	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3727
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Firestone: 5 mm	Fr.R.	Firestone: 5 mm
	Re.L.	Firestone: 8 mm	Re.R.	Firestone: 8 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1057,66
-------------------	----------------

Tailgate, Bump(s), PDR - Knock out without painting	63,00
---	--------------



Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	-------------






No pictures to display

Door panel F L, Tear, Acceptable	0,00
----------------------------------	-------------

No pictures to display

Internal Boot Lining L, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

<i>No pictures to display</i>		
Door R R, Bump(s) and scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Sill outer R, Bump(s), LI - Repair and paint (complete)		430,50
		
Front bumper, Scratch(es), LI - Repair and paint (complete)		211,80
		
Trunk lid covering R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Rocker panel inner F L, Bump(s) and scratch(es), LI - Repair and paint (complete)		115,56
		
Bonnet, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Seat cover F R, Stain, Cleaning		25,00
		
Bumper R, Scratch(es), LI - Repair and paint (complete)		211,80
		
Alloy rim F L polished, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Roof, Stone chip(s), Acceptable		0,00
<i>No pictures to display</i>		
Windscreen, Stone chip(s), Acceptable		0,00
<i>No pictures to display</i>		
Wing F L, Bump(s) and scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim F R polished, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wing R L, Bump(s) and scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Internal Boot Lining R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim R R polished, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		