



|                         |                          |              |                              |
|-------------------------|--------------------------|--------------|------------------------------|
| <b>BMW 3: QF8786</b>    |                          |              |                              |
| Vinnumber:              | <b>WBA8J31040F696288</b> | Versionname: | <b>3 TOURING 318dX 143PK</b> |
| First Registrationdate: | <b>15/07/2014</b>        | Fiscalpower: |                              |
| Expertise Mileage:      | <b>75504</b>             | Power Kw:    | <b>105</b>                   |
| Bodytype:               | <b>Break</b>             | Body color:  | <b>Light Grey</b>            |
| Gearbox:                | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>               |
| Transmission:           |                          | Rims summer: | <b>Aluminium</b>             |
| Fueltype:               | <b>Diesel</b>            | Oil level:   | <b>OK</b>                    |
| Battery functioning:    | <b>Yes</b>               | Parking lot: | <b>4513</b>                  |
| Number of doors:        | <b>5</b>                 |              |                              |
| Number of seats:        | <b>5</b>                 |              |                              |
| Number head rests:      | <b>5</b>                 |              |                              |
| Rims summer:            | <b>Aluminium</b>         |              |                              |
| Category:               | <b>Passenger Car</b>     |              |                              |
| Oil level:              | <b>OK</b>                |              |                              |

|                                |                              |
|--------------------------------|------------------------------|
| <b>Options</b>                 |                              |
| Radio CD                       | Central consol F             |
| Windows electric F             | Luggage cover                |
| Windows electric R             | Rear parking sensors         |
| Cruise Control                 |                              |
| Steering wheel multifunctional |                              |
| Radio multimedia               |                              |
| Type of headlighting           | <b>Headlighting Halogen</b>  |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining semi-leather</b>   |
| Type of climate control        | <b>Autom climate control</b> |

|                                     |           |                     |            |
|-------------------------------------|-----------|---------------------|------------|
| <b>Limited Technical Inspection</b> |           |                     |            |
| Airco functioning                   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile                  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position                       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime                 | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass                        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake                           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                                     |           | Lighting            | <b>OK</b>  |
|                                     |           | Wiperblades         | <b>OK</b>  |

|                       |                                  |                          |       |                          |
|-----------------------|----------------------------------|--------------------------|-------|--------------------------|
| <b>Degree of wear</b> |                                  |                          |       |                          |
|                       | <b>225/50/17/94 W LightMetal</b> |                          |       |                          |
| Summer tyres:         | Fr.L.                            | <b>Bridgestone: 3 mm</b> | Fr.R. | <b>Bridgestone: 3 mm</b> |
|                       | Re.L.                            | <b>Bridgestone: 3 mm</b> | Re.R. | <b>Bridgestone: 3 mm</b> |

|                                       |       |
|---------------------------------------|-------|
| <b>Assistance equipment</b>           |       |
| Total cost ex VAT                     | 74,00 |
| Protection plate M, Tear, E - Replace | 74,00 |



|                               |      |
|-------------------------------|------|
| Wing R R, Bump(s), Acceptable | 0,00 |
|-------------------------------|------|

No pictures to display