



**LAND ROVER RANGE ROVER EVOQUE: MB8882**

Vinnumber:	<b>SALVA5BG2HH190769</b>	Versionname:	<b>SI4 177kW HSE Dynamic Convertible</b>
First Registrationdate:	<b>1/01/2020</b>	Fiscalpower:	
Expertise Mileage:	<b>5512</b>	Power Kw:	<b>177</b>
Bodytype:	<b>Cabriolet</b>	Body color:	<b>Dark Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>4 Weel</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2232</b>
Number of doors:	<b>2</b>		
Number of seats:	<b>4</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Windows electric F	Seats electric F L
Windows electric R	Seats electric F R
Cruise Control	Central consol F
Steering wheel multifunction	Front parking sensors
Seats F heated	Rear parking sensors
Radio multimedia	
Type of headlighting	<b>Headlighting LED</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining leather</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>245/45/20/103 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Continental: 6 mm</b>	Fr.R.	<b>Continental: 6 mm</b>
	Re.L.	<b>Continental: 6 mm</b>	Re.R.	<b>Continental: 6 mm</b>


**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	481,92
Bumper R, Scratch(es), Smart repair	110,64




Ignition key, Missing, E - Replace	150,00
<i>No pictures to display</i>	
Wing R R, Bad repair, Acceptable	0,00



Front bumper, Bad repair, Acceptable 0,00



Wing F R, Bad repair, Acceptable 0,00



Wing R L 3P, Bump(s), Acceptable 0,00

No pictures to display

Wing F L, Bad repair, Acceptable 0,00



Wing R L 3P, Bad repair, Acceptable 0,00

No pictures to display

Door panel F L, Scratch(es), Smart repair 110,64



Door panel F R, Scratch(es), Smart repair 110,64



Centre console, Damaged, Acceptable 0,00

No pictures to display