


MERCEDES CLA: 1GGL552

| | | | |
|------------------------------------|--------------------------|--------------|------------------------------|
| Vinnnumber: | WDD1173011N059846 | Versionname: | CLA BER 200 CDI 136PK |
| First Registrationdate: | 3/02/2014 | Fiscalpower: | |
| Expertise Mileage: | 145694 | Power Kw: | 100 |
| Bodytype: | Berline | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 4129 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | |
|--------------------------------|---------------------------------------|-----------------------|
| Radio CD | | Central consol F |
| Windows electric F | | Front parking sensors |
| Windows electric R | | Rear parking sensors |
| Cruise Control | | |
| Steering wheel multifunctional | | |
| Radio multimedia | | |
| Type of headlighting | Headlighting Xenon | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining semi-artificial leather | |
| Type of climate control | Manual climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | 225/40/18/92 V LightMetal | | | |
|---------------|----------------------------------|--------------------|-------|--------------------|
| Summer tyres: | Fr.L. | Fulda: 3 mm | Fr.R. | Fulda: 3 mm |
| | Re.L. | Fulda: 4 mm | Re.R. | Fulda: 4 mm |

Assistance equipment

| | | | |
|--|------------|------------|--------------|
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 95,00 |
| Alloy rim R R, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Alloy rim F L, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Alloy rim R L, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Front bumper, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Bumper R, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Door F L, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | | | 95,00 |



Tailgate, Scratch(es), Acceptable

0,00

No pictures to display