


PEUGEOT Expert: 1CUK501

Vinnnumber:	VF3XU9HM0BZ070472	Versionname:	EXPERT B/F MWB 229 L2H1 FAP(EU5)90PK
First Registrationdate:	1/03/2012	Fiscalpower:	
Expertise Mileage:	129003	Power Kw:	66
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	IN 13000KM	Parking lot:	TRU20
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Alarm			
Type of headlighting	Headlighting Halogen		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/103 T Steel			
Winter tyres:	Fr.L.	Continental: 7 mm	Fr.R.	Continental: 7 mm
	Re.L.	Continental: 9 mm	Re.R.	Continental: 9 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1767,15
-------------------	----------------

Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	309,13
---	---------------



Bumper F R, Scratch(es), It - Spot repair	115,56
---	---------------



Ignition key, Missing, E - Replace	150,00
------------------------------------	---------------

No pictures to display

Wing R R, Bump(s), Acceptable	0,00
-------------------------------	-------------

No pictures to display

Roof, Bump(s), PDR - Knock out without painting 303,00



Sill outer R, Bump(s) and scratch(es), It - Spot repair 115,56



Separation wall, Bump(s) and scratch(es), E - Replace 250,00



Gear shift lever cover, Tear, E - Replace 9,00



Bodywork, Not original part, Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F L, Stain, Cleaning 25,00



Front bumper, Damaged, E - Replace 398,40



Rearlight L, Crack, E - Replace 91,50

