



SKODA Superb: 1HAB012

Vinnumber:	TMBJJ73TXE9058197	Versionname:	SUPERB COMBI Elegance DSG 105PK Aut.
First Registrationdate:	2/06/2014	Fiscalpower:	
Expertise Mileage:	111220	Power Kw:	77
Bodytype:		Body color:	Brown
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4210
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats R heated	
GPS storage		Seats electric F L	
GPS storage	HD	Seats electric F R	
Windows electric F		Sun Roof electric	
Windows electric R		Panoramic roof	
Cruise Control		Central consol F	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting LED	Type of Tow bar	Tow bar removable
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/91 W LightMetal			
Summer tyres:	Fr.L.	Pirelli: 7 mm	Fr.R.	Pirelli: 7 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 3 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1027,82
-------------------	----------------

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------





Bumper R, Scratch(es), LI - Repair and paint (complete)

278,16



Alloy rim F R, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R L, Scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Bump(s), Acceptable

0,00

No pictures to display

Centre console, Scratch(es), Acceptable

0,00

No pictures to display

Wing R R, Bump(s) and scratch(es), Acceptable

0,00

No pictures to display

Wing F R, Scratch(es), Acceptable

0,00

No pictures to display

Wing F L, Scratch(es), Acceptable

0,00

No pictures to display

Door R L, Scratch(es), Acceptable

0,00

No pictures to display

Luggage space cover, Dirty, Acceptable

0,00

No pictures to display

Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper grille, Broken, E - Replace

34,08



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Trunk lid covering R, Scratch(es), Acceptable

0,00

No pictures to display

Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete)

410,02





Internal Boot Lining R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Front bumper, Scratch(es), It - Spot repair	115,56
---	--------



Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Seat F L compl, Worn, Acceptable	0,00
----------------------------------	------

No pictures to display

Internal Boot Lining L, Scratch(es), Acceptable	0,00
---	------

No pictures to display