


BMW 3: HK4015

| | | | |
|------------------------------------|--------------------------|--------------|--------------------------------|
| Vinnnumber: | WBA3D51030J458586 | Versionname: | 3 BER 320dXA 184PK Aut. |
| First Registrationdate: | 14/03/2014 | Fiscalpower: | |
| Expertise Mileage: | 154440 | Power Kw: | 135 |
| Bodytype: | | Body color: | Grey |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 2527 |
| Battery functioning: | Yes | | |
| Number of doors: | 4 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | |
|--------------------------------|----------------------------------|-----------------------|
| Radio CD | | Central consol F |
| GPS storage | HD | Front parking sensors |
| GPS storage | | Rear parking sensors |
| Windows electric F | | |
| Windows electric R | | |
| Cruise Control | | |
| Steering wheel multifunctional | | |
| Seats F heated | | |
| Radio multimedia | | |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining artificial leather | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| 225/50/17/94 W LightMetal | | | | |
|---------------------------|-------|--------------------------|-------|--------------------------|
| Summer tyres: | Fr.L. | Bridgestone: 7 mm | Fr.R. | Bridgestone: 7 mm |
| | Re.L. | Bridgestone: 6 mm | Re.R. | Bridgestone: 6 mm |

Assistance equipment

| | | |
|---|---------|---------------|
| | Runflat | Yes |
| Total cost ex VAT | | 872,80 |
| Window R R door, Scratch(es), Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |
| Door R R, Scratch(es), Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |
| Door R L, Scratch(es), Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |
| Wing R L, Scratch(es), Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |
| Front bumper, Scratch(es), LI - Repair and paint (complete) | | 211,80 |



| | |
|---|--------|
| Window F R door, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Seat cover R R, Incomplete, E - Replace | 10,00 |
| <i>No pictures to display</i> | |
| Alloy rim F R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper R, Bump(s) and scratch(es), Le - Replace and paint | 651,00 |



| | |
|--|------|
| Rearview mirror housing R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wing F R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Windscreen, Repaired, Acceptable | 0,00 |

