


FORD Focus: 1ELK031

Vinnnumber:	WF0LXXGCBCT37070	Versionname:	FOCUS CLIP. EConetic Titanium 88g 105PK
First Registrationdate:	14/01/2013	Fiscalpower:	
Expertise Mileage:	229200	Power Kw:	77
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2406
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	SD	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/16/93 H Steel			
Winter tyres:	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 559,04

Sill outer R, Scratch(es), E - Replace 113,00

Door R L, Bump(s), Acceptable 0,00

No pictures to display
Rear window, Not original part, Remove lettering 0,00

No pictures to display
Covering interior front pillar R, Damaged, E - Replace 44,60



Door F R, Bump(s), PDR - Knock out without painting 63,00

No pictures to display

Bumper R, Scratch(es), Smart repair 110,64



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Floor covering F L, Damaged, Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Trunk lid covering R, Damaged, Acceptable 0,00

No pictures to display

Centre console, Scratch(es), Acceptable 0,00

No pictures to display

Door catch F L, Missing, E - Replace 16,00



Door F R, Scratch(es), Acceptable 0,00



Interior, Dirty, Acceptable 0,00

No pictures to display

Luggage space cover, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Bump(s), Acceptable 0,00

No pictures to display

Ceiling, Stain, Acceptable 0,00

No pictures to display

Wing R R, Bump(s), Acceptable 0,00

No pictures to display