



PEUGEOT Expert: 1GWX983

Vinnnumber:	VF3XBAHZ8EZ025834	Versionname:	EXPERT MULTI MWB L2H1 Access SV 128PK
First Registrationdate:	22/05/2014	Fiscalpower:	
Expertise Mileage:	139944	Power Kw:	94
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2822
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	6		
Number head rests:	6		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Rear parking sensors	
GPS storage		Type of Tow bar	Tow bar fixed
GPS storage	HD		
Windows electric F			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	NOT OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/99 H Steel			
Winter tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Fulda: 4 mm	Re.R.	Fulda: 3 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	953,38
Trunk lid covering R, Damaged, Acceptable	0,00



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	158,85
---	--------





Front bumper, Bump(s) and scratch(es), E - Replace 398,40



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Trunk door R R, Bump(s), Acceptable 0,00

No pictures to display

Wing R L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Steering wheel, Worn, Acceptable 0,00

No pictures to display

Engine protective plate, Tear, E - Replace 35,00



Seat cover F L, Deformed, Acceptable 0,00

No pictures to display

Roof, Scratch(es), LI - Repair and paint (complete) 361,13

