



SEAT Alhambra: 1GVG491			
Vinnumber:	VSSZZZ7NZEV518463	Versionname:	ALHAMBRA
First Registrationdate:	9/05/2014	Fiscalpower:	E-Ecom.Exec.Limit.136PK
Expertise Mileage:	158763	Power Kw:	100
Bodytype:	MPV	Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2625
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	215/60/16/99 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 2 mm	Fr.R.	Michelin: 2 mm
	Re.L.	Uniroyal: 4 mm	Re.R.	Uniroyal: 4 mm


Assistance equipment	
Total cost ex VAT	693,36
Wing R L, Bad repair, Paint	0,00



Bumper F R, Scratch(es), It - Spot repair	115,56
---	--------



Roof, Chemical polution, LI - Repair and paint (complete) 577,80



Windscreen, Stone chip(s), Windscreen repair 0,00



Door F R, Repaired, Acceptable 0,00

No pictures to display

Door R R, Repaired, Acceptable 0,00

No pictures to display

Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Repaired, Acceptable 0,00

No pictures to display

Wing F R, Bad repair, Paint 0,00



Wing R R, Bad repair, Paint 0,00



Internal Boot Lining L, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Repaired, Acceptable 0,00

No pictures to display