



VOLVO S60: 1JLV324

Vinnnumber:	YV1FS73C1F2354934	Versionname:	S60 BER D4 Kinetic 181PK
First Registrationdate:	21/01/2015	Fiscalpower:	
Expertise Mileage:	108975	Power Kw:	133
Bodytype:	Berline	Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4524
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
Windows electric F		Central consol F	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar fixed
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/50/17/95 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 2 mm	Fr.R.	Michelin: 2 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2877,52
-------------------	----------------

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Bonnet, Scratch(es), LI - Repair and paint (complete)	290,08
---	---------------



Armrest F Mid, Damaged, Acceptable 0,00

No pictures to display

Door frame F L, Bump(s) and scratch(es), It - Spot repair 115,56



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Door panel R L, Damaged, E - Replace 114,00





Door F R, Chemical polution, LI - Repair and paint (complete) 318,35



Door panel R R, Damaged, E - Replace 114,00



Door panel F L, Damaged, E - Replace 114,00



Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68

