



VOLKSWAGEN Golf: 1FLN154

Vinnumber:	VWZZZAUZDW054142	Versionname:	GOLF BER Trendline 105PK
First Registrationdate:	7/08/2013	Fiscalpower:	
Expertise Mileage:	171958	Power Kw:	77
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3425
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	SD	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	
Adaptive cruise control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear


	195/65/15/91 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 1,6 mm	Fr.R.	Michelin: 1,6 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	968,95
-------------------	--------

Door F L, Scratch(es), LI - Repair and paint (complete)	318,35
---------------------------------------------------------	--------



Maintenance book, Missing, E - Replace	0,00
----------------------------------------	------

No pictures to display

Seat cover F R, Stain, Cleaning	25,00
---------------------------------	-------



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Front bumper, Scratch(es), LI - Repair and paint (complete)

211,80



Wing F R, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Bump(s), Acceptable

0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Wing F L, Scratch(es), It - Spot repair

0,00



Gear shift lever cover, Damaged, E - Replace

12,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F L, Scratch(es), Acceptable	0,00
----------------------------------------	------

No pictures to display