



<b>BMW 1: XC8683</b>			
Vinnnumber:	<b>WBA1C71080J953601</b>	Versionname:	<b>1 BER HATCH 116d 116PK</b>
First Registrationdate:	<b>29/09/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>133094</b>	Power Kw:	<b>85</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4707</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

<b>Options</b>			
Radio CD		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
GPS storage			
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining Alcantara</b>		
Type of climate control	<b>Manual climate control</b>		

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
	<b>225/45/17/91 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Bridgestone: 8 mm</b>	Fr.R.	<b>Bridgestone: 8 mm</b>
	Re.L.	<b>Bridgestone: 3,5 mm</b>	Re.R.	<b>Bridgestone: 3,5 mm</b>

<b>Assistance equipment</b>	
Total cost ex VAT	1011,68
Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20

	<b>Front bumper, Damaged, LI - Repair and paint (complete)</b>	<b>211,80</b>
--	--	---------------

	<b>Front bumper, Damaged, LI - Repair and paint (complete)</b>	<b>211,80</b>
--	--	---------------

Door F R, Bump(s), Acceptable 0,00

No pictures to display

Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68



Windscreen, Stone chip(s), Acceptable 0,00

No pictures to display

Roof, Bump(s), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00

