



BMW 3: 1EYR150

Vinnumber:	WBA3D91010F405153	Versionname:	3 BER 316d 116PK
First Registrationdate:	23/04/2013	Fiscalpower:	
Expertise Mileage:	121799	Power Kw:	85
Bodytype:	Berline	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1619
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 W LightMetal			
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Repair kit	Yes	Jack	Yes
------------	------------	------	------------

Total cost ex VAT	2393,94
-------------------	----------------

Door F L, Scratch(es), LI - Repair and paint (complete)	318,35
---	---------------



Roof, Bump(s) and scratch(es), LI - Repair and paint (complete)	481,50
---	---------------





Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Foglight R, Damaged, E - Replace 138,00



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08




Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Door panel F L, Damaged, E - Replace 114,00



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80



Wing R L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18



Tailgate, Chemical polution, LI - Repair and paint (complete) 301,68

