



MERCEDES C: 1DHS270			
Vinnumber:	WDD2042011F915598	Versionname:	C BRE 200 CDI BlueEFF. S&S 136PK
First Registrationdate:	22/05/2012	Fiscalpower:	
Expertise Mileage:	126028	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	B1 IN 125 DGN	Parking lot:	2624
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-leather
Type of climate control	Autom climate control























Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Winter tyres:	225/45/17/91 H LightMetal			
	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Semperit: 8 mm	Re.R.	Semperit: 8 mm

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			1774,85
Roof, Chemical polution, LI - Repair and paint (complete)			481,50



Front bumper, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wing R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wing F L, Scratch(es), Acceptable		0,00

<i>No pictures to display</i>		
Ceiling, Stain, Cleaning		25,00
		
		
Door R L, Chemical polution, LI - Repair and paint (complete)		318,35
		
Tailgate, Bump(s), Acceptable		0,00
<i>No pictures to display</i>		
Wing R L, Chemical polution, LI - Repair and paint (complete)		308,20
		
Seat cover F R, Stain, Cleaning		25,00
		
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)		95,00
		
		
Bumper R, Scratch(es), LI - Repair and paint (complete)		211,80
		
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)		95,00
		
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)		95,00
		
Seat cover R, Stain, Cleaning		25,00



Door R R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

