



FORD Transit 350L: 498BKV

Vinnnumber:	WF0XXXTFXAL57635	Versionname:	TRANSIT 350L B/F LWB
First Registrationdate:	23/03/2010	Fiscalpower:	4x4 Silv.DPF 140PK
Expertise Mileage:	214001	Power Kw:	103
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	4 Weel	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV06
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD	
Windows electric F	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/75/16/113 R Steel			
Winter tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	846,05
Sliding door R, Bump(s) and scratch(es), LI - Repair and paint (complete)	382,02



Roof pillar R, Rust, Acceptable	0,00
---------------------------------	------

No pictures to display

Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete)	232,88
---	--------





Trunk door R R, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Door seal R, Worn, Acceptable 0,00



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Bodywork, Not original part, Acceptable 0,00

No pictures to display

Sill outer L, Rust, Acceptable 0,00



Wing R L, Scratch(es), LI - Repair and paint (complete) 231,15



Roof, Bump(s), Acceptable 0,00

No pictures to display

Windscreen, Repaired, Acceptable 0,00

No pictures to display