


MERCEDES V KLASSE: 1HNT384

| | | | |
|-----------------------------------|-------------------------------|--------------|------------------|
| Vinnumber: | WDF44781313006513 | Versionname: | |
| First Registrationdate: | 1/09/2014 | Fiscalpower: | |
| Expertise Mileage: | 106985 | Power Kw: | 120 |
| Bodytype: | | Body color: | Silver |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 4202 |
| Maintenance | SERVICE A IN 326 DAGEN | | |
| Battery functioning | Yes | | |
| Number of doors | 5 | | |
| Number of seats | 8 | | |
| Number head rests | 8 | | |
| Rims summer | Aluminium | | |
| Category | Passenger Car | | |
| Oil level | OK | | |
| Registration Certificate Car (BE) | Yes | | |

Options

| | | |
|--------------------------------|------------------------------|-----------------------|
| Radio CD | | Central consol F |
| GPS storage | SD | Luggage cover |
| GPS storage | | Front parking sensors |
| Windows electric F | | Rear parking sensors |
| Cruise Control | | |
| Steering wheel multifunctional | | |
| Seats F heated | | |
| Type of headlighting | Headlighting LED | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining leather | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------------|-----------------------|-------|-----------------------|
| | 245/45/18/100 Y LightMetal | | | |
| Summer tyres: | Fr.L. | Semperit: 8 mm | Fr.R. | Semperit: 8 mm |
| | Re.L. | Semperit: 8 mm | Re.R. | Semperit: 8 mm |

Assistance equipment

| | | | |
|-------------|------------|------|------------|
| Spare wheel | Yes | Jack | Yes |
|-------------|------------|------|------------|

| | |
|-------------------|---------|
| Total cost ex VAT | 3014,32 |
|-------------------|---------|

| | |
|---|--------|
| Wing R L, Scratch(es), LI - Repair and paint (complete) | 231,15 |
|---|--------|



| | |
|---------------------------------------|-------|
| Rearlight R, Scratch(es), 67 - Polish | 55,19 |
|---------------------------------------|-------|



Tyre F L, Damaged, E - Replace 105,00



Alloy rim R R polished, Damaged, E - Replace 182,40



Door R R, Scratch(es), LI - Repair and paint (complete) 238,76



Door moulding Lower F R, Strained , E - Replace 91,50



Alloy rim F L polished, Damaged, E - Replace 182,40



Front bumper, Scratch(es), LI - Repair and paint (complete) 158,85



Alloy rim F R polished, Damaged, E - Replace 182,40



Door F L Bump(s) and scratch(es), LI - Repair and paint (complete) 286,76

Door L L, Bump(s) and scratch(es), LI - Repair and paint (complete) 200,00



Door R L, Scratch(es), LI - Repair and paint (complete) 238,76



Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete) 506,02



Wing F L, Scratch(es), LI - Repair and paint (complete) 165,13



Wing R R, Scratch(es), LI - Repair and paint (complete) 231,15



Alloy rim R L polished, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Damaged, LI - Repair and paint (complete) 158,85

