



SKODA Octavia: 1HDE568

Vinnumber:	TMBJG7NEXE0209329	Versionname:	OCTAVIA COMBI GreenLine Ambition 110PK
First Registrationdate:	23/06/2014	Fiscalpower:	
Expertise Mileage:	118492	Power Kw:	81
Bodytype:		Body color	Silver
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	NOT OK	Parking lot	2726
Maintenance	UITVOEREN		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H Steel			
Summer tyres:	Fr.L.	Uniroyal: 3 mm	Fr.R.	Uniroyal: 3 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1288,22
-------------------	----------------

Maintenance, Maintenance, Execute	0,00
-----------------------------------	-------------



Wheel cover F R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete)	301,68
---	---------------



Door frame F L, Bump(s) and scratch(es), It - Spot repair 115,56



Door F L, Bump(s), PDR - Knock out without painting 82,80



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 268,18



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20

